



## Penetrant & Dirt Remover (SC 21)



### Product description

- All-rounder for the effective removal of all types of industrial dirt from various surfaces
- Remover is particularly characterized by its ability to effortlessly remove red and fluorescent penetrant residues
- pH value: approx. 6

### Fields of application

- Ideal for industrial floors, but also worktops and non-corrosive metals
- Excellent results are achieved on almost all sealed floors and good performance on unsealed floors (IMPORTANT: Test on an inconspicuous area beforehand!)
- Contains solvents and may attack paints and plastics under certain circumstances

### Minimum shelf life & temperatures

- Bulk: 3 years at storage temperature
- Storage: +5 °C - +45 °C
- Application temperature: +5 °C - +50 °C



### Application



- Can be used directly or diluted 1:10 with water, depending on soiling
- Allow stubborn stains to soak for 5 to 10 minutes
- A melamine sponge (dirt eraser) is recommended for cleaning smooth surfaces and a pot sponge for rougher surfaces (e.g. industrial floors)

### Further information

Further information is available on request or at [www.mr-chemie.de](http://www.mr-chemie.de).



Watch the application videos now



### Delivery form



\*\*Technical changes reserved!\*\*